

INITIAL INVESTIGATION

SITE NAME: Boulevard Auto Service
ADDRESS: 12459 Des Moines, Seattle
INSP. DATE: 7/10/91
INSP. NAME: John Stormon

✓✓ 2010

An initial investigation was conducted at Boulevard Auto Service on 7/10/91 by John Stormon. This location is now Goldco Building Maintenance. Five tanks were removed, only three were known, and the contaminated soil was excavated. The building was sold in March to the owners of Goldco.

On 7/12/91 I spoke with BJ at Washington Wrecking and was told that the cleanup at this site was not finished yet. A final cleanup report will be forwarded to Ecology within the month.

STATUS: Cleanup Ongoing

PHOTO No. 22

BOULEVARD AUTO SERVICE

DATE: 7/10/91

TIME: _____

TAKEN BY:

STURMON

WITNESS:

FILM: 6514

CAMERA:

E111304

DESCRIPTION:

SITE

COMMENTS:



PHOTO No. _____

DATE: _____

TIME: _____

TAKEN BY:

WITNESS:

FILM: _____

CAMERA:

DESCRIPTION:

COMMENTS:
